# Fall 2012 Levee Maintenance Deficiency Summary Report Overall LMA & Unit Ratings, including USACE Erosion Survey

### Sacramento River Basin

NA0014 Murphy Slough at M&T Ranch	Overall LMA Rating	Total LMA Miles						
	U	0.78						
Rated Item		Maintena	nce Deficiancy		Enforc	ement		k System scence
Nateu Item	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
Earthen Levee								
Vegetation	0.49		0.49	62.82%				
LMA Totals:	0.49	0.00	0.49	62.82%	0.00	0.00	0.00	0.00

## **LMA District Cover Sheet**

### Fall 2012 Levee Inspection Results

# Murphy Slough at M&T Ranch

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)		
* Overall LMA Rating (Fall Only)			U			
	** Non-receipt of Su	mmer or Winter Inspe	ection Reports may effec	ct overall annual rating		
* SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.  FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.						
omments						

### **Unit Cover Sheet**

### Fall 2012 Levee Inspection Results

## Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.78

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			U	
Date of Inspection	04/19/2012 - 04/19/2012		11/08/2012 - 11/08/2012	
DWR Inspector	Bob Duffey		Bob Duffey	
Accompanied By	Jason Cooper Sutter Yard		Jason Cooper Sutter Yard	

#### Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

#### http://cdec.water.ca.gov/lma.html

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

### Levee Inspection Report By Mile - Fall 2012

# Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.78	11/08/2012 11/08/2012	Bob Duffey

LMR	Levee	Mile	Catagory	Item	Location	Rating	Action/Comment	GPS Latitude	e/Longitude	Issue No.
No.	Start	End	Category	пеш	tion	ing +	Action/Comment	Start	End	Photo
1			Earthen Levee	Operations & Maintenance Manuals	LS	A Ma		0 0	0	3
_				_				DWR ID: DWR_NA		
2			Earthen Levee	Emergency Supplies & Equipment	LS	A Ma		0	0	6
								DWR ID: DWR_NA	0014_01_s _ 2012_	_6
3			Earthen Levee	Flood Preparedness & Training	LS	A Ma		0	0	7
								DWR ID: DWR_NA	0014_01_s _ 2012_	.7
4	0.00	0.09	Earthen Levee	Vegetation	LS	M Ma	V4 : Elderberries are blocking visibility and flood fight capability.	39.667708 ° -121.959817 ° -		4 Y
5	0.00	0.20	Earthen Levee	Vegetation	WS	M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	39.667588 ° -121.959495 ° -		1 Y
6	0.00	0.20	Earthen Levee	Vegetation	WS	M Ma	V4 : Elderberries are blocking visibility and flood fight capability.	39.666988 ° -121.960993 ° - DWR ID: DWR_NA		5 Y 5
7	0.11	0.43	Earthen Levee	Vegetation	LS	A Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	39.666747 ° -121.961195 ° - DWR ID: DWR_NA		2 Y

## Levee Inspection Report By Mile - Fall 2012

# Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.78	11/08/2012 11/08/2012	Bob Duffey

Levee Mile Report Line	4				
Start Levee Mile	0.00				
End Levee Mile	0.09				
Location	Land Side				
Category	Earthen Levee				
Item	Vegetation				
View of the elderberries along the I/s toe.					

rduffey\_f\_20120911\_162.jpg

Levee Mile Report Line	5
Start Levee Mile	0.00
End Levee Mile	0.20
Location	Water Side
Category	Earthen Levee
Item	Vegetation
View of the vegetation of	ong the M/C alone

View of the vegetation along the W/S slope.

rduffey\_f\_20120911\_161.jpg

Levee Mile Report Line	6			
Start Levee Mile	0.00			
End Levee Mile	0.20			
Location	Water Side			
Category	Earthen Levee			
Item	Vegetation			
View of the vegetation along the waterside slope				

View of the vegetation along the waterside slope of the levee.

rduffey\_f\_20120911\_163.jpg







\* Location

LS: Land Side

WS: Water Side

CR: Crown

\*\* Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiancy Ob : Design & System Obsolescence En : Enforcement

## **Levee Inspection Report By Mile - Fall 2012**

# Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.78	11/08/2012 11/08/2012	Bob Duffey

Levee Mile Report Line	7			
Start Levee Mile	0.11			
End Levee Mile	0.43			
Location	Land Side			
Category	Earthen Levee			
Item	Vegetation			
View of the levee with all vegetation removed.				
rduffey_f_20121128_362.JPG				

